

L1

Cold Load Pickup Issues
A report to the line protection subcommittee of the Power System Relay Committee
of the IEEE Power Engineering Society
Prepared by working group D1

Abstract

This report describes cold load pickup and inrush problems as they affect protective relaying applications on distribution feeder circuits and provides guidance for protective system applications. A List of pertinent literature and recent studies is provided as well as some real life examples.

Fredric (Fred) A Friend, P.E. Lead Engineer
American Electric Power
Distribution Asset Planning
POB 1986
Charleston, WV 25327-1986

304-746-2675 office
fafriend@aep.com